

S E R V I C E N O T E

SUPERSEDES: 8751A-09B

8751A Network Analyzer

Serial Numbers: 0000J00000 / 9999J99999
 0000A00000 / 9999A99999

Relationship Between the firmware revision and ROM set**Duplicate Service Notes:** None

This service note only provides information about the relationship between the firmware version and the ROM set's part number. IT IS NOT THE PURPOSE OF THIS SERVICE NOTE TO RECOMMEND UPGRADING THE FIRMWARE VERSION WHEN YOU REPLACE FAILED ROMs!

Table A. Firmware (ROM) Revision versus ROM Set PN

Firmware Revision	A1 w/o Opt. 002 Part Number	A1 w/Opt. 002 Part Number	A2 Part Number
1.00	08751-86001	None	08751-86003
2.00	08751-86301	08751-86002	08751-86003
3.xx	08751-86601	08751-86302	08751-86303
4.xx	08751-86901	08751-86602	08751-86403

Continued

DATE: 20 November 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

MT

3355

ADDITIONAL INFORMATION:

NOTE:

1. When replacing the failed ROMs, order the same revision's ROMs and install them.
2. When upgrading the 8751A's revision by a request, the 16298B/C/D must be used. The necessary parts, the manual changes and the modification note are included in it. Refer the modification note for the SRAM replacement and bit switch settings.
3. It is necessary to match the firmware revision between A1 ROMs and A2 ROMs.