

JVC

SERVICE MANUAL

CD RECEIVER

KD-LX10 KD-LX30



Suppliment

Areas suffix

J ----- Northern America

General assembly indication was wrong.
Please change the service manual of
KD-LX10 / KD-LX30.
(Issue No.49537)

General assembly




■ **Parts list (General assembly)**


Block No. M1MM

⚠	Item	Parts number	Parts name	Q'ty	Description	Area
	112	QAR0029001-SA2	FEED MOTOR ASS'Y	1		
	113	PPN13KA10C-SA6	MOTOR ASS'Y	1		

Wrong



Collect





VICTOR COMPANY OF JAPAN, LIMITED
MOBILE ELECTRONICS DIVISION
PERSONAL & MOBILE NETWORK B.U. 10-1,1Chome,Ohwatari-machi,Maebashi-city,Japan