

Date: Feb. 12, 2007
Subject: Performance test Procedures
From: U.S. Service Center

Dear User,

LeCroy has determined that the following tests are not necessary to obtain a traceable calibration, and can be omitted from the appropriate Performance Verification Procedure.

- Erroneous Read/Write Test
- HFREJ trigger coupling for channels 1-4, and external inputs
- Overshoot and Rise time (LeCroy performance procedure requires a 4969A, this pulser is no longer available)
- Overload
- 1 Meg ohm bandwidth tests requiring any special adaptors, ie 4962-8/9/or 10 as these parts are no longer available. A properly adjusted passive probe for the scope model may be used as a substitute, but results may vary.

If you have any questions concerning this change please contact our Service Department at 1-800-553-2769.

Thank you,