

R197.112.I90

Series : SMB CARLOCK



All dimensions are in mm.



*According to FAKRA specifications

Issue: 0334 A

In the effort to improve our products, we reserve the right to make changes judged to be necessary.



_

R197.112.I90

Series : **SMB CARLOCK**

PACKAGING

| Standard | Unit | Other |
|----------|------------|------------|
| 100 | 'W' option | Contact us |

SPECIFICATION

QS9000

ELECTRICAL CHARACTERISTICS

 $\begin{array}{ll} \text{Impedance} & \quad \Omega \\ \text{Frequency} & \quad \text{GHz} \end{array}$

VSWR + 0.000 x F(GHz) Maxi Insertion loss $\sqrt{F(GHz)}$ dB Maxi

ENVIRONMENTAL

Operating temperature -40/+110 ° C

Hermetic seal Atm.cm3/s

Panel leakage

OTHERS CHARACTERISTICS

Assembly instruction Page 3 & 4

Others:

HOUSING FOR COAX R114.082.325,R114.086.325,R114.089.325

MECHANICAL CHARACTERISTICS

Center contact retention

Axial force – Mating end N mini
Axial force – Opposite end N mini
Torque N.cm mini

Recommended torque

Mating N.cm Panel nut N.cm

Mating life 100 Cycles mini

Weight 1.736 g

Issue: 0334 A

In the effort to improve our products, we reserve the right to make changes judged to be necessary.




R197.112.I90

Series : **SMB CARLOCK**

RECOMMENDED MOUNTING PROCEDURE




• Push the coax until it stops at the bottom of the housing





• Push the secondary lock in final position to secure the coax inside the housing (until it click on)



Issue: 0334 A

In the effort to improve our products, we reserve the right to make changes judged to be necessary.



R197.112.I90

Series : **SMB CARLOCK**

RECOMMENDED DISASSEMBLING PROCEDURE




• To unlock the coax from the CPA devise,
push the secondary lock from the

push the secondary lock from the material marking side until it click on





- insert a screw driver between the elastic finger and the slot of the housing as shown on the picture.
- Tip up the screw driver as shown on the picture to lift up the elastic finger and when it is done pull on the cable assembly to remove the coax from the housing.



Issue: 0334 A

In the effort to improve our products, we reserve the right to make changes judged to be

