മ്പ	ПП
	Ш

PAGE:	1/	1
-------	----	---

Model: Kaiser1 Date: 16-Mar-00 No.: MH306001a

MB Correction

The items in bold have been corrected or added.

Modified Article: Parts Catalog Corrections				Prepared by: M. Mano		
From: Technical Ser	rvice Dept., GTS Division					
Reason for	□ Parts catalog correction	☐ Vendor ch	ange	☐ To meet standards		
Modification: ☐ To facilitate assembly ☐ To improve re		e reliability	()			
	☐ Part standardization	☐ Other				

The following part numbers were printed incorrectly in the parts catalog.

Mainframe (H306)

Incorrect	Correct part	Description	Q'ty	Int	Page	Index	Note
part number	number						
G0291906	H3062714	Shutter - LDUNI	1		23	2	<u> </u>
H3062165	H3062178	Pressure Spring	2		33	5	
H3062183	H3062158	Pressure Roller Lever	2		33	6	
H3062181	H3062194	Rear Release Lever	1		33	9	
H3062180	H3062193	Front Release Lever	1		33	12	

SG3 unit (H133)

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
H3066160	H3066162	PCB - SG3 - V34	1		3	2	

The above corrections will be included in the next release of the parts catalog. (For the USA, this will be the first revised version)

RIGON

PAGE: 1/1

Model: Kaiser1				Date: 26-Apr-00		No.: MH306002		
Modified Article: F		Prepared by: M. Mano						
From: Technical Ser		•						
Reason for	Parts catalog correction	☐ Vend	lor ch	ange	☐ To m	neet standards		
Modification:		, ,		☐ To improve reliability		e reliability	()
	☐ Part standardization							

The following are the part numbers for the fusing unit assembly for the Kaiser 1.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-		Fusing Unit	1				USA
-	H3062170	Fusing Unit	1				Eur./Asia


Model: Kaiser1	Date	te: 08-May-00		No.: MH306003		
Modified Article: A	Prepared	by: M.N	Mano			
From: Technical Services Dept., GTS Division				•		
Reason for	Parts catalog correction	☐ Vend	lor ch	ange	☐ To m	neet standards
Modification:		☐ To improve reliability		e reliability	()
	☐ Part standardization	Other				

PAGE: 1/2

The following are the part numbers for the ADF Pickup Unit Assembly for the Kaiser1:

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	H3061207	ADF Pickup Unit	1				*1

^{*1:} This part contains the following items (see the next page for each part number).



RIGOH RIGOHModification Bulletin

Model: Kaiser1 Date: 08-May-00 No.: MH306003

PAGE: 2/2

H3061207 contains the following parts.

		· · · · · · · · · · · · · · · · · · ·		
Index	Part number	Description	Q'ty	Note
1	H5211286	Gear -Feed Roller	1	
2	H5211316	Spring Clutch - M9	1	
3	H3061288	Clutch Roller	1	
4	H0062316	Spacer - Pickup Clutch	2	
5	H5211314	Spring Clutch - M6	1	
6	H3061370	Feed Shaft	1	
7	H3061274	Feed Bracket	1	
8	H3061320	Pressure Spring	1	
9	H3061361	Pickup Idler Gear	3	
10	H5211287	Gear - Pickup Roller	1	
11	H5211288	Collar - Pickup	1	
12	H3061302	Pickup Roller	1	
13	H3061276	Pickup Roller Shaft	1	
14	H3061301	Feed Roller	1	
15	07200040E	Retaining Ring - M4	4	
16	07200030E	Retaining Ring - M3	1	
17	08053480	Bushing - 6mm	1	

NOTE: The parts in bold are PM parts.

RIGOM Modification Bulletin PAGE: 1/5

Model: Kaiser1		e: 08-May-00		No.: MH306004	
Modified Article: F	Parts Catalog Corrections	Prepared by: M.Mano			
From: Technical Se	rvices Dept., GTS Division	1			
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To n	neet standards
Modification:	☐ To facilitate assembly	o facilitate assembly 🔲 To improv		()
	☐ Part standardization	☐ Other			

Please make the following corrections to your parts catalogs.

For all models

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	08053480	Bushing - 6mm	1		15	106	
H3063119	H3063139	Rear Support Plate	1	X/O	47	13	

For all models

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3063180	G0293950	Transfer Roller	1	O/O	27	24	

Schedule: After stock of the old part runs out.

For Europe/Asia, the new part has been used since the first mass production lot.

For all models

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3062158	H3062083	Pressure Roller Lever	1	X/O	33	6	

Schedule: Since February mass production for the USA.

For Europe/Asia, the new part has been used since the first mass production lot.


Model: Kaiser1 Date: 08-May-00 No.: MH306004

PAGE: 2/5

For Europe/Asia *1

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0294161	H3065068	Thermofuse – 169°C	1	X/O	35	8	
-	G0294133	Cover Screw	2		35	35	*2

- *1: These parts have been used since the first mass production lot.
- *2: This part was not included in the original illustration (not a new part). Please add the index description and illustration.




Model: Kaiser1 Date: 08-May-00 No.: MH306004

PAGE: 3/5

For Europe/Asia *1

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3065010	H3065011	PSU	1	X/O	41	26	
H3065207	H3065223	Harness NCU-6P	1	X/O	41	30	
H3065212	H3065224	Harness NCU-4P	1	X/O	41	31	
-	N6074525	Choke Coil RITL-9704	1		41	33	*2

- *1: These parts have been used since the first mass production lot.
- *2: This part was not included in the original illustration (not a new part). Please add the index description and illustration.




Model: Kaiser1 Date: 08-May-00 No.: MH306004

PAGE: 4/5

For Europe/Asia

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	H3063198	Clamp	1		43	33	*1

^{*1:} This part was not included in the original illustration (not a new part). Please add the index description and illustration.



Model: Kaiser1 Date: 08-May-00 No.: MH306004

PAGE: 5/5

For Asia

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
11500024	-	Power Supply Cord	1		41	28	

Power Supply Cord for Asian models has not been contained since May mass production.

SG3 unit for Europe/Asia

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3065207	H3065223	Harness NCU-6P	1	X/O	3	7	

	ΙПЛ
เษษ	儿山

PAGE:	1/1
-------	-----

Model: Kaiser1		te: 05-Jul-00)	No.: MH306005	
Modified Article:	Parts Catalog Corrections		Prepared	l by: M.I	Mano
From: Technical Se					
Reason for	□ Parts catalog correction	☐ Vendor c	hange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliabilit		()
	☐ Part standardization	☐ Other			


Please make the following corrections to your Parts Catalogs.

SG3 (H133)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	54886141	NCU Board – EU/Asia	1		3	1	*1
-	H3064648	Insulation Sheet	1		3	15	*2
	H3064634	Bracket – NCU	1		3	16	*2

^{*1:} This part number was not included in the original table (not a new part).

Please add in the three index descriptions above along with the illustration for the Insulation Sheet and the NCU Bracket (#15 and 16, circled below).



^{*2:} These parts were not included in the original illustration (not new parts).

Œ0	101
II I I I I I I I I	l n l
1(0)(0)	ш

PAGE:	1/3
-------	-----

Model: Kaiser1			te: 25-Aug-0	00	No.: MH306006
Modified Article:	Parts Catalog Corrections	Prepared	by: M.	Mano	
From: Technical Se	ervices Dept., GTS Division	7			
Reason for	□ Parts catalog correction	☐ Vendor d	hange	☐ To r	neet standards
Modification:	☐ To facilitate assembly ☐ To improve reliability		()	
	☐ Part standardization	Other			


Please make the following corrections to your parts catalogs.

For all models: Mainframe (H306)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	H3061334	Sheet ADF Switch 1	1		13	38	*1
-	H3061335	Sheet ADF Switch 2	1		13	39	*1

^{*1:} This part was not included in the original table or illustration (it is not a new part).

Please add in the two index descriptions above along with the illustration for the Sheet ADF Switch 1 and Sheet ADF Switch 2 (#38 and 39, circled below).






PAGE: 2/3

Model: Kaiser1 Date: 25-Aug-00 No.: MH306006

For all models: Mainframe (H306)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H5235003	AW020075	Photointerrupter	1	X/O	21	5	*1
H3063183	H3062099	Decal – Fusing Cover1	1	O/O	27	7	*2
G0293863	G0293967	Discharge Brush	1	X/O	27	18	*3
H3063129	H3063151	FCU Shield Cover	1	X/O	43	11	*4
G0294175	H3062137	Stripper Pawls	1	O/O	35	20	*2
H3063334	H3063197	Adjusting Screw	1	X/O	45	26	*5
	H3063335	Decal Paper Size	1		29	27	*6

- *1: The old part number was misprinted.
- *2: The new part will be used after the old part is out of stock.
- *3: For the USA, the new part will be used after the old part is out of stock. For Europe/Asia, the new part will be used from the first mass production lot.
- *4: For the USA, the new part has been used since April mass production lot. For Europe/Asia, the new part will be used from the first mass production lot.
- *5: For the USA, the new part has been used since the February mass production lot. For Europe/Asia, the new part will be used from the first mass production lot.
- *6: The new part has been added since the June mass production lot. (see the following illustration)



For USA: Mainframe (H306)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3064067	H3064074	Front Cover	1	X/O	7	20	*1
H3064466	H3064450	LCD Decal	1	X/O	9	2	*1
G0294161	H3065068	Thermofuse - 169°C	1	O/O	35	8	*2

^{*1:} This modification is for the Ricoh model (H306-20) only.

The new part has been used since the June mass production lot.

^{*2:} The new part will be used after the old part is out of stock.



PAGE: 3/3

Model: Kaiser1 Date: 25-Aug-00 No.: MH306006

For Europe/Asia: Mainframe (H306)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3064053	H3064072	Upper Cover	1	X/O	7	11	*1
H3062166	H3062078	Exit Roller	1	X/O	33	13	*1

^{*1:} The new part will be used from the October mass production lot.

RIGOH

Modification Bulletin

PAGE: 1/1

Model: Kaiser1	Da	Date: 25-Aug-00		No.: MH306007	
Modified Article: P	arts Catalog Correction	Prepared	l by: M.	Mano	
From: Technical Ser	vices Dept., GTS Division				
Reason for	□ Parts catalog correction	☐ Vendor c	hange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()
Part standardization Other					

Please make the following corrections to your parts catalogs.

PIF (H144)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
-	H3065148	PIF – FCU Harness NA	1		5	1	*1
H3064640	H3064642	Rear Bracket	1	X/O	5	2	*2

^{*1:} This part number is for the USA model only.

(This part number was not included in the original table: it is not a new part)

PFU (H110)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H5194547	A8601140	Spring Plate	1	X/O	3	12	*1
-	H5194736	Balancer	2	X/O	5	20	*2
-	H5194725	Paper Feed Shaft	1	X/O	5	22	*2

^{*1:} The new part has been used since the March mass production lot.

^{*2:} This part number was misprinted.

^{*2:} This part number is for the Asian model (H110-85) only.

(This part number was not included in the original table: it is not a new part)

1തത	ПП
	IHI
1(0)(0)	1111

PAGE: 1/1

Model: Kaiser1	Dat	e: 09-Mar-0	1	No.: мнзо6008		
Modified Article: Parts Catalog Corrections				by: M.	Mano	
From: Technical S	ervices Dept., GTS Division		Ī			
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To r	neet standards	
Modification:	☐ To facilitate assembly	1= '	☐ To improve reliability ()	
	Part standardization	Other				

Please make the following corrections to your Parts Catalogs.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3061350 —	-H3061410	Stepper Motor Ass'y	1	X/O	17		
H3061373 —							
H3065060 _							
H3061351	H3061360	Rear Slow Down Gear	1	X/O	17	22	

^{*} H3061410 contains the stepper motor, the stepper motor cushion and the motor bracket.

In some cases, the stepper motor bracket rattles due to the vibration of the stepper motor, causing a squeaking noise.

To ensure this does not occur, the bracket and rear slow down gear have been modified. In addition, the motor, bracket and cushion have been grouped under one part number (H3061410).

Therefore in the field, all four parts (gear and motor assembly) should be replaced together as a set.

The following are the cut-in serial numbers (applied September 2000): A1400900001~

Π	回	\bigcirc	ПП
$\ \ $	Ŋ	(\mathbb{U})	ᇤ

PAGE: 1/1

Model: Kaiser1			Date: 07-Nov-01		1	No.: MH306009	
Modified Article: k	(aiser1 Parts Catalog Correction	on		Prepared	by: M.	Mano	
From: Technical Services Dept., GTS Division							
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly			()		
	☐ Part standardization	☐ Othe	r				

The following parts have been modified to increase paper feed performance and reliability.

PFU (H110)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H5194717	H3103372	Paper Feed Stay	1	O/O	4	3	
H5194731	H3103368	Paper End Sensor Bracket	1	O/O	4	9	
H5194540	H3103367	Slide Rail	1	O/O	6	5	
H5194756	H3103369	Motor Bracket	1	O/O	6	14	
H5194797	H3103365	Spring Plate	1	O/O	8	5	
H3063501	H3103364	Decal – Size Indication	1	0/0	8	24	
H5194776	H3103373	Paper Tray	1	O/O	8	28	

П	回	M	巾巾
	G	$(\hspace{-0.6pt})$	믮

PAGE: 1/1

Model: Kaiser1			Date	e: 08-Nov-0	1	No.: MH306010	
Modified Article: Kaiser1 Parts Catalog Correction				Prepared by: M.Mano			
From: Technical Ser	vices Dept., GTS Division						
Reason for	☐ Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly	bly		e reliability	()	
	☐ Part standardization	Other	•				

One of the Transport Relay Rollers may shift position along the shaft when clearing a paper feed jam, which can then cause another jam. The roller has been modified to ensure this does not occur.

PFU (H110)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H5194741	H5194742	Transport Relay Roller	1	X/O	6	3	

ገ@ጦ	П
](片(l)	

PAGE: 1/1

Model: Kaiser1 Date				e: 09-Nov-0	1	No.: MH306011	
Modified Article: κ		Prepared by: M.Mano					
From: Technical Services Dept., GTS Division							
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification: ☐ To facilitate assembly ☐ To		☐ To improve reliability		()		
	☐ Part standardization	☐ Othe	r				

Please add the following to your Parts Catalogs.

NA Model (H306-20)

Old part number	New num	:	Description	Q'ty	Int	Page	Index	Note
	H306	4447	Keytop – 10key (Asia)	1		8	24	

RIGOH

Modification Bulletin

PAGE: 1/1

Model: Kaiser1			Date	e: 12-Nov-0	1	No.: MH306012
Modified Article: Kaiser1 Parts Catalog Correction					by: M.I	Mano
From: Technical Services Dept., GTS Division						
Reason for	Parts catalog correction	☐ Vend	lor ch	ange	☐ To m	neet standards
Modification:	☐ To facilitate assembly	□ To improve reliability		e reliability	()
	☐ Part standardization	☐ Othe	r			

In some cases, the printed text on the number pad keys and Stop key can wear off after extended use. The following have been modified for increased reliability.

NA Model (H306-20)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3064401	H3064408	Operation Panel Ass'y (NA)	1	X/O	8	1	
H3064448	H3064481	Keytop – 10key (NA)	1	X/O	8	24	
H3064441	H3064479	Keytop – Stop	1	X/O	8	26	

NA OEM Model (H306-29)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3064402	H3064409	Operation Panel Ass'y (NA)	1	X/O	8	1	
H3064448	H3064481	Keytop – 10key (NA)	1	X/O	8	24	
H3064441	H3064479	Keytop – Stop	1	X/O	8	26	

Europe Model (H306-30/40/60)

	_	•					
Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3064403	H3064410	Operation Panel Ass'y (EU)	1	X/O	8	1	
H3064442	H3064478	Keytop – 10key (EU)	1	X/O	8	24	
H3064441	H3064479	Keytop – Stop	1	X/O	8	26	

Asia Model (H306-51/59)

- 10 101 1110 0101							
Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3064404	H3064411	Operation Panel Ass'y (Asia)	1	X/O	8	1	
H3064447	H3064480	Keytop – 10key (Asia)	1	X/O	8	24	
H3064441	H3064479	Keytop – Stop	1	X/O	8	26	

ገ@ጦ	П
](片(l)	

PAGE: 1/1

Model: Kaiser1				e: 15-Nov-01		No.: MH306013			
Modified Article: Kaiser1 Parts Catalog Correction					Prepared by: M.Mano				
From: Technical Services Dept., GTS Division									
Reason for	□ Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards			
Modification:	☐ To facilitate assembly	☐ To improve reliability		e reliability	()			
	☐ Part standardization	☐ Other	r						

Please add the following to your Parts Catalogs.

OEM Models (H306-23/30)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	H3063156	AIO Cap (Lanier, Info)	1	-	44	27	

RIGOH

Modification Bulletin

PAGE: 1/1

Model: Kaiser 1			Date	ate: 05-Dec-01		No.: MH306014		
Modified Article: Kaiser1 Parts Catalog Correction				Prepared by: M.Mano				
From: Technical Se	rvice Dept., GTS Division							
Reason for	Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability ☐ Other		e reliability	()		
	☐ Part standardization							

To minimize the effect on the environment, the chromium in the following parts has been removed.

NA Models Only (H306-20/23/29)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3064702	H3064712	Hand Set Bracket 2	1	0/0	6	23	

All Models

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3061099	H3061115	Stopper Bracket	1	0/0	10	1	
H3061258	H3061458	R0 Bracket	1	0/0	12	18	
H3061259	H3061459	R1 Bracket	2	0/0	16	16	
H3061375	H3061475	Tightener Bracket	1	0/0	16	25	
H3061410	H3061510	Stepper Motor Ass'y	1	O/O	16	-	*1
H3063141	H3063241	Lock Lever Stay	1	O/O	26	29	
H3063118	H3063218	Front Support Plate - Short	1	O/O	36	2	
H3063135	H3063235	Drive Shaft Support Plate	1	O/O	36	3	
H3064066	H3064075	Operation Panel Bracket 2	1	O/O	42	17	
H3063157	H3063257	AIO Sensor Bracket	1	O/O	42	22	
H3063175	H3063275	AIO Cap (NA)	1	0/0	44	27	
H3063176	H3063276	AIO Cap (EU)	1	0/0	44	27	
H3063156	H3063256	AIO Cap (Lanier, Info)	1	0/0	44	27	

^{*1:} When replacing the Stepper Motor Assembly, be sure to also replace the Rear Slow Down Gear (H3061360) at the same time. Please see MB #MH306008.

Cut-in Serial Numbers:

Lanier: 1082176 ~

Others: A1410800001~

$\Box \alpha$	کار	M	ПП
IJĽ	ワし	0)	لآلا


PA	G	E :	1	11

Model: Kaiser1 Date			nte: 20-Dec-0)1	No.: MH306015
Modified Article: P	arts Catalog Corrections	Prepared	l by: M.	Mano	
From: Technical Service Dept., GTS Division					
Reason for	☐ Parts catalog correction	☐ Vendor o	hange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	□ To impro	□ To improve reliability)
	☐ Part standardization	☐ Other			

It is possible for the fusing harness cover to become warped due to heat (rare occurrence). To prevent this, its composition has been changed from plastic to metal. Please make the following corrections to your Parts Catalogs.

For all models

	Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
Ì	G0294138	H3062179	Fusing Harness Cover	1	X/O	34	9	



മ്പ	ПП
ᢆᡛ	Ш

PAGE: 1/1

Model: Kaiser1 Date				e: 4-Mar-02		No.: MH306016
Modified Article: K	Prepared	by: M.N	Mano			
From: Technical Ser	vice Dept., GTS Division					
Reason for	☐ Parts catalog correction	☐ Vendo	r cha	ange	☐ To m	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		ereliability	()
	□ Part standardization	☐ Other				

The Pickup Roller has been changed due to parts standardization with the new model Kaiser 3 (to be released in the near future).

Note:

- 1. The color of the new roller is gray (the previous roller was black). Since there is no difference in performance (int. 0/0), both rollers can be used for both models.
- 2. The new roller will not be used on the Kaiser 1 production line.

Mainframe (H306)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3061302	H3061292	Pickup Roller	1	0/0	14	20	

间 侧	ПП
	I N I

Model: Kaiser1

Reason for

Modification:

Modification **B**ulletin

Dat	e: 3-Oct-02		No.: MH306017
	Prepared	by: M.I	Mano
ept.			
☐ Vendor ch	•	☐ To m	neet standards)

PAGE: 1/1

The following parts have been changed due to parts standardization with the K-3, and are made of a stronger material.

Other

For all models

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3062193	H3102173	Front Release Lever	1	0/0	32	12	
H3062194	H3102174	Rear Release Lever	1	0/0	32	9	

For Europe and Asia models only

Modified Article: Parts Catalog Corrections

From: Technical Services sec. Service Planning Dept.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3062078	H3102193	Exit Roller	1	0/0	32	13	

\sim	пп
Œ0	1 4 1
	l n l
ω	uu

PAGE:	1	/1
-------	---	----

Model: Kaiser 1		ate : 9-Jan-03		No.: MH306018	
Modified Article:	Parts Catalog Corrections	Prepared	l by: M.	Mano	
From: Technical S	Services Sec. Service Planning D				
Reason for	□ Parts catalog correction	☐ Vendor	change	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()
	☐ Part standardization	☐ Other			

The following part has been changed due to parts standardization with the K-3

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0291972	H3102701	Shield Glass	1	O/O	45	20	

മ	ጠ	ПП
ரு	(Ш

PAGE: 1/

Model: Kaiser 1 Date				e: 23-Jan-0	3	No.: MH306019		
Modified Article: Parts Catalog Corrections					by: M.	Mano		
From: Technical Services Sec. Service Planning Dept.								
Reason for	Reason for			ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improv		☐ To improve reliability		e reliability	()
	☐ Part standardization	☐ Othe	r					

The following part has been changed to increase paper feed reliability.

Mainframe (H306)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H5193021	H5193321	Rear Side Fence	1	X/O	29	23	
H5193332	H5193322	Front Side Fence	1	X/O	29	5	

	ПП
(ՄյՄ	Ш

PAGE: 1/

Model: Kaiser 1 Date				e: 23-Jan-0	3	No.: MH306020
Modified Article: Parts Catalog Corrections					by: M.	Mano
From: Technical Services Sec. Service Planning Dept.						
Reason for	Reason for Parts catalog correction			ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly ☐ To improv		nprove	e reliability	()
	☐ Part standardization	☐ Othe	r			

The following part has been changed to increase paper feed reliability.

PFU (H110)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H5194781	H3103376	Separation Hook - Front	1	X/O	9	11	
H5194782	H3103377	Separation Hook - Rear	1	X/O	9	15	

	ПП
(ՄյՄ	Ш

PAGE: 1/1

Model: Kaiser 1 D			Date	e: MH30602	21	No.: MH306021
Modified Article: Parts Catalog Corrections			Prepared	by: M.	Mano	
From: Technical Ser						
Reason for	□ Parts catalog correction	tion		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improv		e reliability	()
	☐ Part standardization	☐ Othe	r			

The following parts have been changed due to parts standardization with the Model K3.

Mainframe (H306)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
H3063125	H3103125	Interlock Switch Cover	1	O/O	37	10	
G0291064	H3105072	Toner End Sensor	1	O/O	31	20	

PFU (H110)

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AX200129	H3105042	Magnetic Clutch	1	0/0	5	24	
H3103364	_	Decal - Size Indication	1→0	-	9	24	
H5194784	H3103378	Bottom Plate	1	X/O	9	25	

	旧

Model: Kaiser 1

Reason for

Modification:

Modification **B**ulletin

	Date	e: 23-Jan-0	3	No.: мн	306022
		Prepared	by: M.	Mano	
ept.					
☐ Vend	or ch	ange	☐ To n	neet standa	ards
☐ To improve reliability			()	

PAGE: 1/1

The material of the following part has been changed to increase paper feed reliability.

Mainframe: Other than Lanier (H306)

Modified Article: Parts Catalog Corrections

From: Technical Services Sec. Service Planning Dept.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3063361	H3063371	Transport Cover	1	X/O	25	13	

Other

Mainframe: Lanier (H306)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3063338	H3063372	Transport Cover (Lanier)	1	X/O	25	13	

വയി	怬
	ய

Р	А	G	E:	1	/1

Model: Kaiser 1 Date			e: 7-Jan-04		No.: MH306023		
Modified Article: Parts Catalog Corrections					Prepared by: T.Shintani		
From: 1st Technical Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction ☐ Vendor ch		lor ch	ange	☐ To m	neet standards	
Modification: ☐ To facilitate assembly ☐ To im		nprove	e reliability	()		
	☐ Part standardization	Othe	r				

The material of the following part has been changed to improve the endurance of the pressure roller bushing.

<Symptom>

Poor fusing was found in the field as the pressure roller bushing was shaved. A chip on the axis of the pressure roller caused the problem.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0294120	H3062197	Pressure Roller	1	O/O	33	15	