മ്പ	叽
<b>(GO</b>	ய

Model: Russian-C2 ADF (DF75) Date			e: 4-Jul-02		No.: MB386001	
Modified Article: Magnet Catch					by: S.	Tomoe
From: Technical Services sec. Service Planning Dept.						
Reason for	☐ Parts catalog correction			ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve		e reliability	(	)		
	☐ Part standardization	☐ Othe	r			

The following part has been changed due to a vendor change:

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8591181 —		Magnet Catch	2		9	5	
	─ B3514135	Magnet Catch - Original Table	2	0/0	9	5	

$\sim$	пп
(GO	II n I

Modification:

Model: Russian-C2 ADF (DF75)

Modified Article: Timing Belt

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

□ Part standardization

### Modification Bulletin

Date: 5-Jul-02			No.: MB386002			
Prepared by: S. Tomoe						
ept.						
☐ Vendor change			☐ To m	neet standards		

)

**PAGE: 1/1** 

The following has been changed due to parts standardization with the Model A-C2 ADF.

Other

☐ To improve reliability

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B3864171	AA043929	Timing Belt – B40S2M114	1-1	0/0	13	25	

# RIGOH

#### Modification Bulletin

etin Page: 1/1

Reissued: 23-Oct-02

Model: Russian-C2 ADF (DF75)	Date: 15-Jul-02	No.: MB386003a
------------------------------	-----------------	----------------

#### **MB Correction**

The items in bold italics have been corrected or added.

Modified Article: Left Cover			Prepared by: S. Tomoe		
From: Technical Services sec. Service Planning Dept.					
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To meet standards	
Modification:	☐ To facilitate assembly			( )	
	☐ Part standardization	☐ Other			

When the document approaches the transport rollers, it can sometimes contact the pullout lever due to warping in the left cover. The left cover has been changed to reduce the possibility of this happening.


Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
<b>B386</b> 4841	<b>B386</b> 4842	Left Cover	1	X/O	3	8	

Dongan (Jima) i i	201941 (011114) 1 10440401									
MODEL NAME	DESTINATION	CODE	SERIAL NO.							
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0918100001							
DF75	Infotec	B386-26	4M68910237							

Model: Russian-C2 ADF (DF75) Date			e: 15-Jul-02	1	No.: MB386004	
Modified Article: Cover Sponges				Prepared by: S. Tomoe		
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vendor ch		ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve			e reliability	(	)	
	☐ Part standardization	☐ Othe	r			

The following protective padding has been added to facilitate easier handling of the Platen Cover sheet.

New part	Description	Q'ty	Page	Index	Note
number					
A8584871	Cover Sponge - Front	1	3	23	
A8584872	Cover Sponge - Front Right	1	3	24	



MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0927400001
DF75	Infotec	B386-26	4M6852xxxx

മ്പ	叽
<b>(GO</b>	ய

Modification:

Model: Russian-C2 ADF (DF75)

Modified Article: Main Control Board

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

# Modification Bulletin

Date: 15-Jul-02				No.: MB386005	5
		Prepared	by: S.	Tomoe	
ept.					
☐ Vendor change			☐ To m	neet standards	
☐ To improve reliability			(	)	

**PAGE: 1/1** 

The Main Control Board has been changed to further ensure original non-feeds do not occur.

Old part number	New part number	Description	Q'ty	Page	Index	Note
B3865520	B3865530	Main Control Board	1-1	13	2	

Other

MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0918100001
DF75	Infotec	B386-26	4M68910001

രി	ПΠ
60	LnJ

Modification:

Model: Russian-C2 ADF (DF75)

Modified Article: Reverse Drive Roller

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

## Modification Bulletin

○ Other

Date: 15-Jul-02			l I	No.: MB3860	06
		Prepared	by: S.	Tomoe	
ept.					
☐ Vendor change			☐ To n	neet standards	
☐ To improve reliability			(	)	

**PAGE: 1/1** 

To eliminate noise occasionally generated by the Reverse Roller, the width of the D cutout in the roller has been reduced.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A8583140	B3863140	Reverse Drive Roller	1-1	X/O	9	27	

MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0918100001
DF75	Infotec	B386-26	4M68910001

വത്ത	ПП
(GO	LnJ

**PAGE: 1/1** 

Model: Russian-C2 ADF (DF75) Date			e: 15-Jul-02		No.: MB386007	
Modified Article: Main Control Board				Prepared by: S. Tomoe		
From: Technical Services sec. Service Planning Dept.Tech						
Reason for Parts catalog correction Vendor ch			or ch	ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve			e reliability	(	)	
	☐ Part standardization	Othe	r			

The ADF Main Control Board software has been changed to further ensure proper erase margin adjustment at the trailing edge of the original.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B3865530	B3865560	Main Control Board	1-1	X/O	13	2	

MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0918407265
DF75	Infotec	B386-26	4M68120001

# RIGOH

### Modification Bulletin

etin Page: 1/1

R	ei	ss	ue	d:	29-ر	lul	-02
---	----	----	----	----	------	-----	-----

Model: Russian-C2 ADF (DF75)	Date: 15-Jul-02	No.: MB386008a
------------------------------	-----------------	----------------

#### **MB Correction**

The items in bold italics have been corrected or added.

Modified Article: Main Control Board			Prepared by: S. Tomoe		
From: Technical Services sec. Service Planning Dept.					
Reason for	Parts catalog correction	☐ Vendor change		☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve	e reliability	( )	
☐ Part standardization ☐ Other					

The Main Control Board software has been modified to ensure proper communication between the ADF and Model U-C1.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3865560	B3865565	Main Control Board	1-1	X/O	13	2	

- 3- \ -1							
MODEL NAME	DESTINATION	CODE	SERIAL NO.				
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0927600001				
DF75	Infotec	B386-26	4M68420001				

രി	ПΠ
60	LnJ

Modification:

Model: Russian-C2 ADF (DF75)

Modified Article: Original Scale

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

### Modification Bulletin

Date: 15-Jul-02				No.: MB3860	009
		Prepared	by:		
ept.					
☐ Vendor change		☐ To n	neet standards	;	
☐ To improve reliability			(	)	

**PAGE: 1/1** 

To improve scanning accuracy when this ADF is installed on the Model U-C1, ribs have been added to the Original Scale.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3867101	B3867102	Original Scale	1-1	X/O	3	16	

○ Other

MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J09277030001
DF75	Infotec	B386-26	4M6882xxxx

വത്ത	ПП
(GO	LnJ

**PAGE: 1/1** 

Model: Russian-C2 ADF (DF75) Date			e: 15-Jul-02		No.: MB386010	
Modified Article: M		Prepared by: S. Tomoe				
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve		e reliability	(	)
	☐ Part standardization	Other				

To ensure that ACS functions properly when using this ADF on the Model U-C1, the diameter of the roller shaft has been increased from 6 mm to 8 mm.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8593120	B3863121	Middle Transport Roller	1-1	X/O	11	10	

MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0927700001
DF75	Infotec	B386-26	4M68520001

# RIGOH

### Modification Bulletin

etin Page: 1/1

Reissued: 8-Aug-02

Model: Russian-C2 ADF (DF75)	Date: 15-Jul-02	No.: MB386011a
------------------------------	-----------------	----------------

#### **MB Correction**

The items in bold italics have been corrected.

Modified Article: Decal – Exposure Glass			Prepared by: S. Tomoe			
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vendor ch	ange	☐ To meet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability		( )		
	□ Part standardization	☐ Other				

The following has been changed due to standardization with the Model A-C2 ADF.


Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3796063	G5646076	Decal – Exposure Glass	1-1	X/O	3	19	

MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J09277030001
DF75	Infotec	B386-26	4M6882xxxx

Model: Russian-C2 ARDF (DF75) Date			ate	e: 19-Jul-02		No.: MB386012
Modified Article: Mylar Seals				Prepared	by: S.	Tomoe
From: Technical Services sec. Service Planning Dept.						
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly	☐ Vendor change ☐ To improve reliability		-	☐ To m	neet standards )
	☐ Part standardization	Other				

To cover the holes near the sensors and provide further shielding from static electricity, the following seals have been newly added.

New part number	Description	Q'ty	Page	Index	Note
B3864691	Mylar Seal - 28X107	1	5	41	
B3864692	Mylar Seal - 16X45	1	5	42	
B3864693	Mylar Seal	1	5	40	





tion **B**ulletin Page: 2/2


No.: MB386012

Date: 19-Jul-02

Model: Russian-C2 ARDF (DF75)

#### NOTE:

The Mylar Seal (B3864693) should be positioned under the Paper Size Sensor Board (B3865540) as shown:




MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0927600001
DF75	Infotec	B386-26	4M68420001

Model: Russian-C2 ADF (DF75) Date			e: 19-Jul-02	1	No.: MB386013	
Modified Article: C		Prepared by: S. Tomoe				
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vend		-	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve		nprove	e reliability	(	)	
	☐ Part standardization	Othe	r			

To increase the latitude against electromagnetic interference when this ADF is installed on the Model U-C1, a Relay Harness has been added.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8595702	B4895715	Original Tray Harness	1-1	X/O	5	29	
	B4895713	Relay Harness – Original Tray	0-1	7/0	5	43	



Dongan (Onna) i i	<u>oaaotioii</u>		
MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0927600001
DF75	Infotec	B386-26	4M68420001

വത്ത	ПП
(GO	LnJ

Modification:

Model: Russian-C2 ADF (DF75)

Modified Article: Torsion Spring

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

### Modification Bulletin

	Date	e: 19-Jul-02		No.: MB38601	4
Prepared			by: S.	Tomoe	
ept.					
☐ Vendor change			☐ To n	neet standards	
☐ To improve reliability			(	)	

**PAGE: 1/1** 

To ensure proper ACS performance when this ADF is installed on the Model U-C1, the following parts have been changed.

○ Other

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8593318	B3863318	Front Torsion Spring	1-1	X/O	9	7	
A8593319	B3863319	Rear Torsion Spring	1-1	X/O	9	9	
A8591722	G4123611	Guide Mylar	1-1	X/O	9	15	
A8593130	B3863130	Exit Drive Roller	1-1	X/O	9	18	


MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0927600001
DF75	Infotec	B386-26	4M68420001

Model: Russian-C2 ADF (DF75) Date			e: 24-Jul-02	!	No.: MB386015	
Modified Article: Platen Cover Sheet				Prepared	by: S.	Tomoe
From: Technical Services sec. Service Planning Dept.						
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly	☐ Vendor change ☐ To improve reliability		-	☐ To n	neet standards )
	☐ Part standardization	Othe	r			


When this ADF is installed on the Model U-C1, the left side of the Platen Cover Sheet rides on the left scale, making it necessary to adjust the sheet position to ensure proper scanning. To facilitate this, the sheet has been changed so that it can be removed easily (fixed by Velcro), and the sheet and sponges have been registered as an assembly.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G4123721		Platen Cover Sheet	1-0		15	2	
A8593614—		Sponge – Left Platen Cover	1-0		15	4	
A8593613—		Platen Cover Sponge	1-0		15	5	
L	<b>►</b> B3863630	Sheet Ass'y	0-1	X/O	15	2	

#### Before modification:



#### After modification:





PAGE: 2/2

Model: Russian-C2 ADF (DF75) Date: 24-Jul-02 No.: MB386015


MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN	B386-17	J0927500001
DF75	Infotec	B386-26	4M68320001

Model: Russian-C2 ADF (DF75) Date			e: 27-Nov-03		No.: MB386016	
Modified Article: Pick up holder and Pulley					by: Y.	Ohtani
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor ch		ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve		e reliability	(	)		
	□ Part standardization	☐ Othe	r			

The following have been changed for the Russian-SC to further ensure that the shaft of the Pickup Holder for the Pulley is not damaged. This change has also been applied to the Russian-C for purposes of parts standardization.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A8592151	G4123821	Holder - Pick Up	1	X/X	7	25	
A8592168	G4123831	Pulley - 22Z	1	X/X	7	27	

**Note:** When installing for the first time, the above parts must be replaced together as a set.




MODEL NAME	DESTINATION	CODE	SERIAL NO.
DF75	All RICOH subsidiaries, NRG, SAVIN, LANIER	B386-17	J0937606687
DF75	Infotec	B386-26	4M68530001

Model: Russian-C2 ADF (DF75) Date			ate: 26-0	Dec-03	No.: MB386017
Modified Article: Exposure Glass Decal				ared by: `	Y. Ohtani
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other		I— ,	meet standards )

The following decal has been added to prompt the operator to clean the exposure glass to ensure black lines do not appear on the copy.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G5646087	DECAL:EXPOSURE GLASS:MACHINE OR COP	0-1	X/O	3	25	



[2 origin (orima) reduction]								
MODEL NAME	DESTINATION	CODE	SERIAL NO.					
DF75	All RICOH subsidiaries, NRG, SAVIN, LANIER	B386-17	J0937300001					
DF75	Infotec	B386-26	4M68130001					