## RIGOH


## Technical Bulletin

PAGE: 1/1

Model: Catleya (E-700 Controller)			Date: 08-Dec-00		No.: RA257045
Subject: E-700 Parallel Cable Included By Mistake			Prepared by: C. Tsuji		
From: Technical Services Dept., GTS Division					
Classification:	<ul> <li>Troubleshooting</li> <li>Mechanical</li> <li>Paper path</li> <li>Other ( )</li> </ul>	Part informati		Service manual revision	

## SYMPTOM

From the beginning of the mass-production of E-700, a parallel cable was included in the carton by mistake.



The following table shows the cut-in serial number for correct production without the parallel cable.

Ship Date	Code & Destination	EFI Part Number	EFI Serial Number	Ricoh Serial Number
10/30/00	G936-01 (US)	45013122	J00002625	P4609400082
10/30/00	G936-02 (INTL)	45015850	J00002639	P4609450550

## SOLUTION

If a parallel cable is included, discard it. (This cable cannot be used for system installation or printing. E-700 does not support a parallel interface.)