RIGOH

Modification Bulletin

PAGE: 1/1

Reissued: 20-May-05

IMOGEL Model 0-CT interchange Unit Type 1232 Date: 22-Mar-05 INO.: MB481001a	Model: Model U-C1 Interchange Unit Type 1232	Date: 22-Mar-05	No.: MB481001a
--	--	-----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Parts catalog correction			Prepared by: S. Tomoe		
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To meet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization ☐ Other				

Incorrect	Description	Page	Incorrect	Correct	Note
part number			Index	Index	
AA080156	Bushing – M4	3	5	6	
52054527	Spring - Exit	3	6	5	

Change/Reason: The index for these parts were corrected.

RIGOH

Modification **B**ulletin

etin	PAGE: 1/1

Model: Model U-C1 Interchange Unit Type 1232 Date		e: 29-Mar-05		No.: MB481002				
Modified Article: Decal				Prepared by: S. Tomoe				
From: 1st Tech. Support Sec. Service Support Dept.								
Reason for	☐ Parts catalog correction	s catalog correction		ange	☐ To meet standards			
		☐ To improve reliability		e reliability	()		
	Part standardization							

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AA003021	AA003023	Decal – Exit Grip	1-1	X/O	3	20	

Change: The illustration on the decal was changed. **Reason:** To make it easier for the operator to clear a paper jam.

RCL (Japan) Production

Model	V/Hz	Destination	Code	Serial Number
Interchange unit	120/60	All RICOH subsidiaries,	B481-17	J3740800001
type 1232	220-240/50, 60	NRG, SAVIN, infotec		

RIGOH

Modification **B**ulletin

PAGE: 1/1

Reissued: 12-Apr-05

Model: Model U-C1 Interchange Unit Type 1232	Date: 29-Mar-05	No.: MB481003a
--	-----------------	----------------

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Solenoids			Prepared by: S. Tomoe			
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To meet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliabili		()		
	☐ Part standardization ☐ Other					

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AA145816	AA143653	Tension Roller Shaft	1-1	O/O	3	4	
B3004574	G3054574	Shaft Guide Plate	1-1	O/O	3	14	
B3004514	B4814514	DC Solenoid – Gate Pawl Lower	1-1	O/O	5	2	
B4815439	B4815493	Gate Unit Harness	1-1	O/O	5	9	
B3004503	B4814503	DC Solenoid – Gate Pawl Upper	1-1	0/0	5	10	

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.