Technical Bulletin

	PAGE: 1/1
Nov-04	No.: RB121009

Model: Model K-C2 Printer/Scanner Option (B622)		Date: 19-Nov-04		No.: RB121009		
Subject: Wrong Installer on LAN-FAX Driver CD-ROM			Prepared by: A. Ishiyama			
From: 1st Tech. Support Sec. Service Support Dept.						
Classification:	Troubleshooting	☐ Part information☐ Electrical☐ Transmit/receiv		tion 🖂 Action required		
	☐ Mechanical			☐ Servi	Service manual revisionRetrofit information	
	☐ Paper path			eive		
	Other ()					

This RTB only applies to the China/Taiwan versions of the Printer/Scanner option (B622-21).

Symptom

The LAN-FAX does not work if it is installed with "Auto Run" on the CD-ROM v1.00 or v1.01.

Cause

Firmware bug:

The installer program for "Auto-run" installs the wrong driver (M3).

Note: The LAN-FAX works fine if it is installed with "Add Printer," because this program installs the correct driver (M4).

Workaround in the field

Install the LAN-FAX driver with "Add Printer" (not "Auto-run").

Solution

Firmware modification.

Applied from: CD-ROM v1.02, December 2004 production