വയയ	吅
]GO	ய

Reason for

Modification:

Model: Model-J P1c

Modified Article: Transfer Unit

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Date: 2-Aug-04		No.: MG082001	
Prepared by: H.Taguchi			
t.			
☐ Vendor change		☐ To m	neet standards
☐ To improve reliability		()

PAGE: 1/2

The transfer unit has been modified from a transfer brush to a transfer roller system in order to further improve the accuracy of color line positioning.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0773841	G0773842	Transfer Unit:Ass'y	1 - 1	X/O*	37	19	

Other

Note*: In accordance with this change, the following firmware upgrade and SP mode setting should be done at transfer unit installation.

Firmware Upgrade, SP Settings at Transfer Unit Installation

- Model J-P1b, Model J-P1CF -

1. Upgrade to the following firmware.

Model:	Code:	Engine Firmware:	System Firmware:
Model J-P1b	G060	B1.28 or newer	2.22 or newer
Model J-P1CF	G060 + G570	B1.28 or newer	1.12 or newer

- 2. Do the following to allow the machine to detect the new unit..
 - 1. Access SP2-399-001 [Trans_Cur_Chg] and select "1".
 - 2. Select "OK".
 - 3. Exit SP mode and turn the main switch Off/On.

Number:	Description:	Default Setting:	Adjustable Range:
SP2-399-001	Trans_Cur_Chg	0	0: Transfer Brush Type
			1: Transfer Roller Type



Modification Bulletin

Date: 2-Aug-04 No.: MG082001

PAGE: 2/2

- Model J-P1c -

Model: Model-J P1c

1. Upgrade to the following firmware (SP mode setting is automatically performed).

Model:	Code:	Engine Firmware:	System Firmware:
Model J-P1c	G082	C1.28 or newer	(Unnecessary)

- ➤ The firmware for models J-P1c and J-P1b are different (ex. C1.28 vs. B1.28).
- If installing the new transfer unit on a J-P1c machine with Engine B1.28 or newer already installed, and you wish to update to a C-version firmware with the same numeric name (e.g. from B1.28 → C1.28), please be sure to 1) first downgrade to B1.27 and then 2) install C1.28 or newer. This is because it is not possible to directly update a Bxxx version to a Cxxx version with the same numeric name.