



ROHDE & SCHWARZ

Test and Measurement
Division

Release Notes

International Keyboards

for R&S Spectrum Analyzer/ Signal Analyzer

➤	R&S FSL	1300.2502.xx
➤	R&S FSP(XP)	1164.4391.xx
➤	R&S FSU(XP)	1166.1660.xx
➤	R&S FSQ(XP)	1155.5001.xx
➤	R&S FSG(XP)	1309.0002.xx
➤	R&S FMU	1303.3500.02

New Features:

- Installation of the German, Spanish, French, Italian and Portuguese keyboard support

Release Note Revision: 2

Contents

History	2
General Topics	2
Installation of the international keyboard support	2
Known Problems	4

History

<u>Date</u>	<u>Rel Note Rev</u>	<u>Changes</u>
02.05.2007	1	First revision
21.05.2008	2	Pictures and instrument R&S FSG added.

General Topics

This update will enhance the embedded XP operating system of the following keyboard layouts:

- **German Keyboards**
- **Spanish Keyboards**
- **French Keyboards**
- **Italian Keyboards**
- **Portuguese Keyboards**

Installation of the international keyboard support

For the installation of the German keyboard support, proceed with the following steps:

- 1) Copy the file **FsxInternationalKeyboards.msi** onto USB stick for floppy disk.
- 2) Connect keyboard and mouse to the analyzer.
- 3) Switch the analyzer on and wait until the boot process is finished.
- 4) Terminate the analyzer firmware by pressing <ALT> <F4>.
- 5) Start Windows Explorer
- 6) Start the installation procedure with double click onto the file **FsxInternationalKeyboards.msi**.
- 7) Reboot the analyzer.
- 8) Now open the windows start menu by pressing the windows key or <CTRL> <ESC>.
- 9) Select *Settings - Control Panel - Regional and Language Options - Languages*.



10) Select *Details*.



11) Select *Add*, choose one of the available input languages and confirm with OK and the dialog will be close.

12) Now change the *Default input language* as needed and close all open dialogs with OK.



13) Reboot the analyzer.

Known Problems

A base system firmware 4.3x (for FSG: V4.39 SP1) or newer is required to support the international keyboard driver. In older versions some of the front panel keys will not work properly.