

SERVICE BULLETIN

(Pages: 1 of 1)

Unifor	ELECTRONICS		SERVI	CE	BULLETI	IN			
Product :	19" CRT monitor	r	Bulletin No. :	01	-C/M-E0064				
Model :	PN19MT		Bulletin Date :		26-Feb-02				
			ECN Date :		26-Feb-02				
SUBJECT:	Humming noise	from power supply in DPM	S mode						
Background :	_	OMT has some humming noise							
	It is caused by the power smart IC that is switched to audio frequency(500Hz) when it enter into off-mode								
	We are going to modify the circuit at March, If you are requested service about this problem, please repair the monitor with below mothod.								
Model name :	PN19MT (S/T 9	6P)							
Solution	Remove the resis	stor R624.							
Application Dat	e : Feb.26,2002								
			1	,	erchangeability Code:	* I.C)			
Location	OLD (before) Parts		NEW	NEW (changed) Parts					
Nia	CEC Code	Decemination	CEC Code		Decemination	TC			

					(Interchangeability	y Code: *	I.C)
Location	OLD (bef		NEW (changed) Parts				*	
No.	SEC Code	Descript	ion	SI	EC Code	Description		I.C
Type	A type	B type	C type	;	D type	E type	F type	2
Interchange	OLD Early	OLD ——Early	OLD	Early OI	LD—Early	Parts Addition	Parts dele	etion
Type Code	(Parts) (Prod.)	(Parts) (Prod.)	(Parts)	Prod.) (Pa	arts) (Prod.)	(None New)	(Old D	Del.)
(* I.C)	NEW Late	NEW Late	NEW	Late NI	EW—► Late			
Application	Reference () Only	Defected se	ts ()	O Whol	le sets ()	1	
Attachment	Schematic l	Diagram ()	Comp	onent La	ay-out ()	Exploded V	View ()	
	Mechanical	Diagram (0)	agram (0) None ()			Others ()		
Product Month: - Augall				ial No. (~	~ from)			
Published by : C.J.Oh Checked by : C			y : C. K.Pa	ark	Approved	by : Y.K.Yoo		

Revision (V8.1 : July 30, 1997) ... Customer Satisfaction Group