

TELEVISION TECHNICAL BULLETIN

MODELS DV5101H DV5103H

SYMPTOM Various symptom as shown below:

Stuck in standby
Picture distorted
White picture
No OSD
Loss of tuning
No remote control functions

CAUSE IC1404 (TVPO) on the digital PWB.

ACTION Replace IC1404 using the part number given below.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
IC1404	IC, TVPO	RH-IX1443BMN3	AY