

## TELEVISION TECHNICAL BULLETIN

---

**MODELS**      28HW53H                      32HW53H

**SYMPTOM**    Low Scart Input levels after replacing the NVM

**ACTION**        Re-write the data as shown below in the NVM

Page 08 Address 60 Value 00

Page 08 Address 61 Value 2A

---

**Sharp Electronics (UK) Limited**

Reference JR27022002-2

Revision 1



White – Carry out as required  
Yellow – Carry out as required and whenever the unit comes in for service  
Red – Carry out on all units