

TELEVISION TECHNICAL BULLETIN

<u>MODELS</u>	51CS03H	51CS05H	59CS03H	59CS05H
	66CS03H	66CS05H		

SYMPTOM Doming caused by high beam current in limited areas of the CRT shadowmask causing short term purity errors.

ACTION Reduce the customer brightness and contrast settings to a point at which doming does not appear.

Note that these levels then need to be stored while in the user picture set up menu.