

TELEVISION TECHNICAL BULLETIN

MODELS 51AT15H

SYMPTOM Intermittent failure of Q602 (line output transistor).

CAUSE Supply line variations.

ACTION Replace C713 with the type listed below.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
C713	Capacitor, 1000uF 105°C	VCEAHA1CN108M	AD

Sharp Electronics (UK) Limited CE Technical Support Group

Originator *Asu* Supervisor _____ Approval Date ___ / ___ / ___ Reference **UK74501X**

White - Carry out as required Yellow - Carry out as required and whenever unit comes in for service Red - Carry out on all units

