

TELEVISION TECHNICAL BULLETIN

MODELS 66GS62H

SYMPTOM Unit intermittently will not start up from standby, shuts down or the line collapses.

CAUSE Q606 intermittent. This transistor is part of the protection feedback circuit.

ACTION Replace Q606 using the part number given below.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
Q606	SMD Transistor, 2SC2412	VS2SC2412KQ-1	AA

Sharp Electronics (UK) Limited

Reference JR10012003-1

Revision 1

White – Carry out as required

Yellow – Carry out as required and whenever the unit comes in for service

Red – Carry out on all units