

TELEVISION TECHNICAL BULLETIN

Subject : Failure of R612

REASON R612 fails for no apparent reason.

ACTION Replace R612 and increase the value of R633 to 2.2Ω ½w.

Note: R633 and R612 are safety components and must be replaced with the parts listed below.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
R612	2.2Ω ½W	RR-XZ0204BMZZ	AB
R633	2.2Ω ½W	RR-XZ0204BMZZ	AB