

TELEVISION TECHNICAL BULLETIN

MODELS DV5932H DV5935H DV5937H DV6635H

 66AS06H

SYMPTOM Poor or no east/west correction.

CAUSE L604.

ACTION Replace L604.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
L604	Coil	RCILP0104CEZZ	AG