

## TELEVISION TECHNICAL BULLETIN

**MODELS**      DV5932H                      DV5935H                      DV5937H  
                         DV6635H

**REASON**      It may be possible for C619 to fail and cause the line output transistor to fail short circuit intermittently.

**ACTION**      Whenever a service call is made to one of the above models, please replace C619 using the part number listed below.

<b><u>REF NO</u></b>	<b><u>DESCRIPTION</u></b>	<b><u>PART NUMBER</u></b>	<b><u>PRICE CODE</u></b>
C619	Capacitor 0.56nF, 250V	RC-FZ6564BMNJ	AB

