

SONY

car stereo Service Bulletin No.72

Technical Department
Sony Service Company
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5/R7

Date: November 24, 1986

Subject: Test Jig - Cord Miswiring

Symptom:
(**)

When using the test jig for the CDX-5 and CDX-R7, check to see that the extension cords are wired correctly end to end. Careful attention should be paid to the RF test cord to ensure that the connector on the RF PCB and the jack on the main PCB maintain the same pin-to-pin connections.