

# SONY

## car stereo Service Bulletin No.77

Technical Department  
Sony Service Company  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-A10

Date: June 26, 1987


Subject: Incorrect Part Number -  
IC-1001 (TL-1451 ACN)

**Symptom:**  
(\*\*)

The part number listed in the service manual on page CD-77 for IC-1001 is not correct. This part number corresponds to a flat pack configuration for TL-1451 instead of a DIP configuration. Note the correct part number below:


Ref. No.	Description	Part Number	
		Incorrect	Correct
IC-1001	TL-1451 ACN Switching Regulator Controller	8-759-908-95	8-759-937-35

TL-1451CNS



8-759-908-95

TL451ACN



8-759-937-35