

SONY

car stereo Service Bulletin No.87

Technical Department
Sony Service Company
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-6100

Date: October 16, 1987

Subject: Incorrect Part Number - Nut,
Flange (Ref. No. 3)

Symptom:

(**)

The flanged nuts on the control shafts which are used to secure the radio in the dashboard of the vehicle have the incorrect part number in the service manual. These nuts are shown as reference number 3 on page 22 of the service manual. Please note the correct part number below:

Solution:

Ref. No.	Description	Part Number	
		Incorrect	Correct
3	Nuts, Flange	4-304-511-00	<u>3-575-039-00</u>

