

SONY

car stereo Service Bulletin No. 91

Technical Department
Sony Service Company
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-747R/787R

Subject: Part Number Correction -
D810 → D815

Date: December 28, 1987

Symptom:
(**)

The part number listed in the service manual on page 46 for diode D810 → D815 is incorrect. Please note the correct part number shown below:

Solution:

Reference No.	Description	Part Number	
		Incorrect	Correct
D810 → D815	Chip LED-Yellow	8-719-920-28 CL-10PG	8-719-920-26 CL-10D

