

SONY

car stereo Service Bulletin No. 92

Technical Department
Sony Service Company
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-50/70

Date: December 28, 1987

Subject: Tape Deck Mechanism Parts
Change - Reference No. 385,
387, 388


Symptom: (**)

During the production of the XR-50/70 car stereo, a change was made in the tape deck mechanism. The parts which are affected are shown below. The specific portion of the part that was changed is also shown (Fig. 1).

Solution:

The new parts and old parts are not compatible with one another. Only the new parts are available from Kansas City Parts. If any one of these three parts must be changed in a unit containing the old parts, all three parts must be changed. The part numbers for the three parts have not been changed from the originals.

Ref. No.	Description	Part Number
385	Link Ass'y, Function, Holder	X-3573-817-0
387	Lever Ass'y, Joint	X-3573-819-0
388	Plate Ass'y, Lock	X-3573-820-0



2CS1287-2

Printed in USA