

SONY

**Car Stereo
Service Bulletin**

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-A10

No. 103


Subject: Missing Part Number

Date: May 23, 1988

Symptom:
(**)

The part number for the flex connector, which connects switch PCB (Ref 913) and LCD PCB (Ref 920), is not listed in the manual.

Solution: The part number is 1-620-083-11.



Compact Disc
CSA-14

Reference: FAX # A880427

PRINTED IN U.S.A.
CSA-14488-8