

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-A10

No. 106

Subject: Replacement Of Flexible PCB


Date: July 29, 1988

Symptom:
(**)

The flexible PCB (Part Number 1-617-350-11) is no longer available.

Solution: It has been replaced with two new flexible PCBs.

Description	Part Number
SD (A) Flexible PCB	1-620-082-11
SD (B) Flexible PCB	1-620-083-11



Compact Disc

CSA-14

Reference:

PRINTED IN U.S.A.
CSA-14788-3