

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XE-8

No. 115

Subject: Display Is Dark Or Does Not
Light Up

Date: November 18, 1988

Symptom:
(13)


The display is too dark or does not light up.

Solution: Please replace the florescent lamp.

Description	Part Number
Florescent Lamp	1-518-622-11

Precautions:

1. Bend the lead at least 1mm away from its base.
2. Do not twist the lead after bending it.



Reference: T/N DS-088-0053

PRINTED IN U.S.A.
CSA-141188-4

Miscellaneous
CSA-14