

SONY.

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7180

No. 142

Subject: Incorrect Part Number For
IC501, IC601

Date: June 28, 1989

Symptom:
(**)

The part number for IC501 and IC601 is incorrectly listed in the service manual.

Solution: Please correct your service manual with the part number listed below:

Designation	Description	Part Number	
		Former	New
IC501	Output IC	8-759-981-39	8-759-981-45
IC601	Output IC	8-759-981-39	8-759-981-45

CSA-14 Tuner / Tape Deck