

SONY

Car Stereo
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-6080

No. 163

Subject: Part Number Correction - IC601

Date: February 16, 1990

Symptom:
(**)

The part number listed in the service manual for IC601 is incorrect.

Solution: Please note the correct part number as shown below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
IC601	LA-4445 Output IC	8-759-801-11	1-806-801-11

CSA-14 Tuner / Tape Deck