

SONY.

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7100

No. 166

Subject: Incorrect Part Number

Date: March 16, 1990

Symptom:
(**)

The part number for the Pilot Lamp PL-201 is incorrect in the service manual.

Solution: Please note the correct part number listed below in your service manual:

| Description | Part Number |
|-------------------|--------------|
| Pilot Lamp PL-201 | 1-518-619-11 |

CSA-14 Tuner / Tape Deck