

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-6020/-6060,-R77, -R79

No. 170R1

Subject: Part Number Correction

Date: July 31, 1990


This Service Bulletin supercedes Service Bulletin No.170

Symptom:
(**)

The part number for the guide feed is incorrect.

Solution: Please correct your service manual with the part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
	Guide, Feed	2-640-654-03	2-643-412-02



Reference: FPR L0683

PRINTED IN U.S.A.
CSA-14790-5

CSA-14 Compact Disc