

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey, 07656

Model: XR-7070, XR-7077

No. 188R1

Subject: Incorrect Part Numbers - Q9/10/
301/325/329

Date: April 26, 1991


This Service Bulletin Supersedes Car Stereo Service Bulletin No. 188.

Symptom:
(**)

The part numbers and descriptions for the following transistors have been incorrectly listed in the service manual.

Solution: Please correct your service manual with the part numbers and descriptions listed below:

Ref. No.	Description		Part Number	
	Incorrect	Correct	Incorrect	Correct
Q9, Q10, Q301, Q325, Q329	2SB-1175HFE	2SB-1132QR	8-729-119-76	8-729-920-78



Reference: FPR L1411, M0969

PRINTED IN U.S.A.
CSA-14491-4

Radio/Cassette
CSA-14

Car Stereo Service Bulletin No.188R1

