

SONY

**Car Stereo
Service Bulletin**

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-R77/R79


No.190

Subject: IC301 Incorrectly Installed

Date: January 7, 1991

Symptom:
(**) IC301 was mistakenly installed 90 degrees out of position.
The factory has been made aware of this, and has corrected the problem.

Solution: Please check all PCBs ordered from stock to confirm proper positioning of IC301 as shown below:



Reference:

PRINTED IN U.S.A.
CSA-141290-4

CSA-14 Compact Disc