

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-7520/7540/7560/7580

No. 357

Subject: Part Number Correction: IC502.

Date: March 17, 1995

Symptom:

(**)

The part number shown in the service manual for IC502 is incorrect.

Solution:

Please make the following correction to your service manuals:

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
IC502	IC, BU4081BF	8-759-937-86	8-759-932-86



Filename: CAR0357.SB
Directory: J:\SBDOC\MAR95
Template: C:\WINWORD\S_BULL.DOT
Title:
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 03/17/95 4:00 PM
Revision Number: 2
Last Saved On: 03/17/95 4:00 PM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 0 Minutes
Last Printed On: 04/01/96 9:29 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 113 (approx.)
Number of Characters: 649 (approx.)