

# Car Stereo Service Bulletin

**CSA-14**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** CDX-5060

**No.** 363

**Subject:** Part Number Correction - Reference No. SW818,  
Switch (Vol -)


**Date:** May 1, 1995

**Symptom:**

(\*\*) The part number listed on page 43 of the Service Manual for Ref # SW818, Switch (Vol -), is incorrect.

**Solution:** Please note the correct part number as shown below.

| REF   | DESCRIPTION    | PART NUMBER  |              |
|-------|----------------|--------------|--------------|
|       |                | INCORRECT    | CORRECT      |
| SW818 | SWITCH (VOL -) | 1-692-386-21 | 1-572-704-21 |



Reference: FPR Q0597  
Autoflagged - NO



PRINTED ON RECYCLED PAPER

PRINTED IN USA





Filename: CAR0363.SB  
Directory: J:\SBDOC\MAY95  
Template: C:\WINWORD\S\_BULL.DOT  
Title:  
Subject:  
Author: Hoyt Wing Lee  
Keywords:  
Comments:  
Creation Date: 05/01/95 10:56 AM  
Revision Number: 2  
Last Saved On: 05/01/95 10:56 AM  
Last Saved By: Hoyt Wing Lee  
Total Editing Time: 1 Minute  
Last Printed On: 04/01/96 9:39 AM  
As of Last Complete Printing  
Number of Pages: 3  
Number of Words: 118 (approx.)  
Number of Characters: 677 (approx.)