

SONY.

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5070/5270/5470

No. 370

Subject: Eliminating Static Noise When Using Extension Flex Cable.

Date: May 17, 1995

Symptom:
(54)

When using the extension flex cable (part number J-2502-011-1) for troubleshooting the CD section, static noise may be heard from the speakers.

Solution: Temporarily remove C-302 on the Main board. Replace C-302 when troubleshooting is finished.

