Car Stereo Service Bulletin



Sony Service Company - Technical Services A Division of Sony Electronics Inc. Sony Drive, Park Ridge, New Jersey 07656

Model:XM-C2000No.385Subject:Service Manual Correction: IC902 Pinouts.Date:December 14, 1995Symptom:
(**)The pinouts shown for IC902 in the service manual are invest.Service Manual Correction: IC902 in the service manual are invest.Date:

Solution: Please make the following correction to your service manual.



