

# Car Stereo Service Bulletin

**CSA-14**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XR-C210

**No.** 386

**Subject:** Preventing Recurring Damage To Sub-panel.

**Date:** December 14, 1995

**Symptom:**

(63)

Replacing a broken sub-panel without also replacing the mounting screws with a different type may lead to recurring damage to the sub-panel.

**Solution:**

When replacing a broken sub-panel, also replace the mounting screws shown in the drawing.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
12	PANEL, SUB	3-916-373-01	SAME	SAME
#8	SCREW, +PTT 2.6 X 6 (S)	7-621-773-95	SCREW, +B, 2.6 X 6	3-932-551-01

