

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MDX-60**No. 398****Subject: Noise In Between Tracks And During Quiet Passages.****Date:** April 29, 1996**Symptom:****(54)**

Audible noise may be heard in between tracks, and when audio passages are at low levels.

Solution:

If the customer complains of this problem, remove D560 on the Main MCB.

Applicable Serial Numbers : up to 15998

