

CONFIDENTIAL

CSA-14

Sony Service Company
National Technical Services
A Division of Sony Electronics Inc.
Park Ridge, New Jersey 07656

Service Bulletin Car Stereo

Model: EXR-11, XR-1400

No. 401

Subject: SOUND LEVEL IS LOW IN ONE CHANNEL

Date: July 3, 1996

Symptom:

(152)

The sound level is low in either the Left or Right channel. The symptom may occur in some models due to a defective variable resistor.

Solution:

If this problem is found to be caused by a defective RV503, remove it and replace it with a new one.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
RV503	RESISTOR, VARIABLE	1-223-818-11	RESISTOR, VARIABLE	1-223-818-11

