

CONFIDENTIAL

CSA-14

Sony Service Company National Technical Services A Division of Sony Electronics Inc. Park Ridge, New Jersey 07656

Service Bulletin Car Stereo

Model: CDX-2100, CDX-C410, CDX-C510, CDX-C610,

No. 412

CDX-C710, CDX-C810DSP, EXCD-21, EXCD-31, EXR-300, EXR-400, EXR-500, XR-3500MK II, XR-C223, XR-C300, XR-C500, XR-C700, XR-C900,

XR-6700

Subject: AVAILABILITY OF POWER HARNESS CABLE. Date: January 6, 1997

Symptom:

Reference: ME-96030

(**) The power cord (16 pin connector) is now available for the models listed. The

harness distributes speaker outputs also. The cord does not have a fuse protect and

each pinout may be different by the models.

NOTE: Please refer to the service manual for the detailed pinout configurations.

Solution: Order the Power Cord extension jig below.

REF	DESCRIPTION	PART NUMBER
-	EXTENSION CABLE (16PIN)	J-2502-013-3

