

**SONY**

**Car Stereo  
Service Bulletin**

Sony Service Company Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** DTX-10


**No.** 201

**Subject:** Service Manual Correction;  
Schematic Diagram, Power Board

**Date:** June 12, 1991

**Symptom:**  
(\*\*) The 7.5 volt supply line is drawn incorrectly on the schematic.

**Solution:** Please make the following correction on Page 46 of your Service Manual:



CSA-14 DAT

Reference: FPR M1012

PRINTED IN U.S.A.  
CSA-14591-8