

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-R79

No. 204

Subject: Incorrect Part Number - L403

Date: June 26, 1991

Symptom:
(**)

The part number for L403 listed in the Service Manual is not a valid part number in the KCP System.

Solution:

The correct part number for inductor L403 is as follows:

Reference	Description	Part Number	
		Incorrect	Correct
L403	Micro Inductor	1-408-578-11	1-410-524-41

CSA-14 CD Player