

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey, 07656

Model: XES-P1

No. 214

Subject: Part Number Correction: IC405 (Control Board)

Date: October 18, 1991

Symptom:
(**)

The part number for IC405 on the control board, shown on page 53 of the Service Manual, is incorrect.

Solution:

Please make the following correction to your Service Manual:

REF.	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
IC405	SN74HC165NS	8-759-236-49	8-759- 236-49 23

CSA-14 Pre-Amp/Signal Processor

Reference: FPR M2493

PRINTED IN U.S.A.
CSA-141091-2