

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-7520/7540/7560/7580/5040/5080

No. 216 R1

Subject: Part Number Correction: L-401

Date: August 14, 1992

THIS SERVICE BULLETIN SUPERSEDES CAR STEREO SERVICE BULLETIN NO. 216

Symptom:
(**)

The part number shown in the Service Manual for L-401 is incorrect:

Solution:

Please make the following correction to your Service Manual:

REF.	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
L-401	INDUCTOR 68 μ H	1-408-419-00	1-410-519-11

CSA-14 CD Player