

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: RM-X2

No. 217

Subject: Part Number Addition: L304


Date: October 31, 1991

Symptom:
(**)

RM-X2 "A" printed circuit boards which were manufactured according to the diagrams shown in Service Manual Supplement 2 have a coil (L304) which was not used on earlier production boards.

Solution: Please add the following part number to page 14 of the original service manual (the supplements do not have part lists).

REFERENCE NUMBER	DESCRIPTION	PART NUMBER
L304	INDUCTOR, 33 μ H	1-408-068-00



Reference: FPR L0260

PRINTED IN U.S.A.
CSA-141091-6

CSA-14
Miscellaneous