

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XM-3040F

No. 221

Subject: Part Number Correction, Front Panel Switches

Date: December 31, 1991

Symptom:
(**)

The part number listed in the Service Manual for Front Panel Switches S501, S502, S503 and S504 is incorrect.

Solution: Correct your Service Manual with the part number shown below:

REFERENCE	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
S501 S502 S503 S504	SWITCH, SLIDE	1-527-753-11	1-572-753-11

CSA-14 Amplifier