

SONY.

Car Stereo Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5080

No. 223

Subject: Part Number Correction: M902

Date: January 20, 1992

Symptom:
(**)

The part number for the spindle motor M902 shown in the Service Manual is incorrect.

Solution:

Please make the following correction on pages 40 and 50 of your Service Manual.

| REFERENCE | DESCRIPTION | PART NUMBER | |
|-----------|---------------------|--------------|--------------|
| | | INCORRECT | CORRECT |
| M-902 | MOTOR, DC (Spindle) | 1-541-560-11 | 1-541-448-41 |

