

SONY.

**Car Stereo
Service Bulletin**

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-6020/R77

No. 229

Subject: Transistor Q702 Is Missing From The Service Manual





Date: March 13, 1992

Symptom:
(**)

Transistor Q702, the LED, LAMP DRIVE is not shown in the Service Manual schematic or board layout.

Solution: Please refer to CDX-R79 Service Manual for the location and part number of Q702.

REFERENCE NUMBER	DESCRIPTION	PART NUMBER
Q702	TRANSISTOR 2SB1122-T	8-729-804-42



Reference: FPR N0325

PRINTED IN U.S.A.
CSA-14292-1

CSA-14 CD Player